

PRICE LIST OF PARTS

WILLCOX & GIBBS Adjustable Tension Sewing Machine



WILLCOX & GIBBS SEWING MACHINE CO.

Home Office: 658 BROADWAY, Cor. Bond Street
NEW YORK, N. Y.

Branches:

BALTIMORE, MD., 321 No. Howard St.	NEWARK, N. J. . . 23 Academy St.
BOSTON, MASS. . 363 Boylston St.	NEW YORK, N. Y. . 239 Fifth Ave.
BROOKLYN, N. Y. 218 Livingston St.	PHILADELPHIA, PA. 131 So. 12th St.
CHICAGO, ILL. . . 17 No. State St.	SAN FRANCISCO, CAL., 504 Sutter St.
CINCINNATI, OHIO . 206 W. 7th St.	ST. LOUIS, MO. . 209 No. 10th St.
LOUISVILLE, KY. . 643 So. 4th Ave.	ST. PAUL, MINN. . . 98 E. 6th St.
LOS ANGELES, CAL . 825 W. 7th St.	WASHINGTON, D.C., 702 10th St., N.W.
MINNEAPOLIS, MINN., 118 So. 8th St.	TROY, N. Y., Fulton and Fourth Sts.

Willcox & Gibbs Sewing Machine Co., Ltd.

LONDON


PARIS

MILAN

BRUSSELS

WILLCOX & GIBBS

ADJUSTABLE TENSION SEWING MACHINE



List No	List Price	Name of Parts
8000—	\$1.77	Arm or Lever, (E)
8001—	.72	Arm Stud or Lever Stud, (a), 3 sizes, .507, .510, .515
8002—	.27	Arm Thread Pin or Short Thread Pin, (u)
8003—	.60	Ball Stud, (y)
6001—	.08	Ball Stud Nut
8004—	.03	Braider Wire
8005—	1.92	Cloth Plate, 7 or 12 stitch, (Q)
8006—	1.92	Cloth Plate, 5 stitch
8007—	1.92	Cloth Plate, 3 stitch
8008—	1.92	Cloth Plate, Blank
8009—	.08	Cloth Plate Bushing, Threaded
8010—	.05	Cloth Plate Bushing, Not Threaded
8011—	.10	Cloth Plate Screw
8012—	.32	Collar, (I)
6034—	.06	Collar Screw, (m)
8013—	1.65	Connection Rod, with Screws (F)
8014—	.05	Connection Rod Screw
8015—	.03	Connection Rod Screw Nut
8016—	1.14	Feed Bar, 12 stitch
8017—	1.14	Feed Bar, 7 stitch (N)
8018—	1.14	Feed Bar, 5 stitch

PRICES SUBJECT TO CHANGE WITHOUT NOTICE


ATTACHMENTS FOR MANUFACTURERS MADE TO ORDER

List No	List Price	Name of Parts
8019—	\$1.26	Feed Bar, 3 stitch
8020—	.04	Feed Bar Leather
8021—	.24	Feed Bar Leather, per foot
8022—	.05	Feed Bar Spring
8023—	.08	Feed Bar Spring, 3 stitch
8024—	.20	Feed Bar Stud, (h), 3 sizes, .264, .268, .272
8025—	.24	Feed Cam, with Leather Pad, 12 stitch
8026—	.24	Feed Cam, with Leather Pad, 7 stitch, (P)
8027—	.24	Feed Cam, 3 stitch
8028—	.10	Feed Cam Leather Pad, 12 stitch
8029—	.10	Feed Cam Leather Pad, 7 stitch
8030—	.09	Feed Cam Screw, (i)
8031—	.39	Feed Cam Screw, 3 stitch
6059—	.06	Feed Cam Screw Spring Washer, (j)
8032—	.05	Feed Cam Screw Washer, 3 stitch
8033—	.05	Feed Cam Stop Pin
8034—	1.26	Feed Surface, (O), 12 stitch
8035—	1.26	Feed Surface, 7 stitch
8036—	1.95	Feed Surface, 3 stitch
8037—	.05	Feed Surface Screw
8038—	.05	Feed Surface Screw, 3 stitch
8039—	.03	Feed Surface Washer, Differing Thicknesses
8040—	.87	Foot, (U)
8041—	.60	Foot, Short (For Umbrella Work)
8042—	.50	Foot, Split
8043—	.50	Foot, Narrow
8044—	1.02	Foot, Long Stitch, (3 stitch)
8045—	.50	Foot, Blank
8046—	.10	Foot Screw, Hexagon Head
8047—	.03	Foot Washer
8048—	.81	Foot Bar, (S), 14 sizes, .253, .256, .258, .260, .262, .264, .266, .268, .270, .272, .274, .276, .278, .280
8049—	.12	Foot Bar Spline
8050—	.06	Foot Bar Spring, (T)
8051—	.06	Foot Bar Spring, Large
8052—	.02	Foot Bar Spring Pin
8053—	.20	Foot Bar Bushing
8054—	.18	Frame Bent Thread Pin, (v)
8055—	.30	Frame Bent Thread Pin, Long
8056—	1.08	Friction Pad, Complete, (W)
8057—	1.14	Friction Pad, with Large Hole, Complete
8058—	.03	Friction Pad Screw, (p)
8059—	.08	Friction Pad Screw, Large
8060—	.09	Friction Pad Spring (o)
8061—	.03	Friction Pad Spring Lever (q)
8062—	.02	Friction Pad Spring Screw
8063—	.60	Glass Washer, (2)
8064—	.37	Guide
6111—	.25	Guide Screw
8065—	1.44	Hook, (L)
8066—	1.44	Hook, with Round Shank
8067—	1.44	Hook, with Hole
8068—	2.16	Hook, Left Hand
6120—	.06	Hook Screw
8069—	.51	Hook Guard, (M)
8070—	.51	Hook Guard, 3 stitch
8071—	.05	Hook Guard Screw
8072—	.18	Hook Guard Screw, Long Stitch, (3 stitch)
6059—	.06	Hook Guard Screw Spring Washer
8073—	1.77	Lever, (E)
	.72	Lever Stud, (a), 3 sizes, .507, .510, .515 Same as 8001
6124—	.03	Lever Stud Washer, Differing Thicknesses
8075—	.87	Lifter, (V)
8076—	.10	Lifter Screw, (r)
8077—	1.74	Needle Bar, (R), 14 sizes, .253, .256, .258, .260, .262, .264, .266, .268, .270, .272, .274, .276, .278, .280

PRICES SUBJECT TO CHANGE WITHOUT NOTICE

ATTACHMENTS FOR MANUFACTURERS MADE TO ORDER

List No	List Price	Name of Parts
6134—	\$.06	Needle Bar Nut, (e)
8078—	.60	Needle Bar Screw, (b), 10 sizes, .380, .385, .390, .395, .400, .405, .410, .415, .420, .425
8079—	.55	Needle Bar Screw, with Nut and Washer, Complete
8080—	.06	Needle Bar Screw Nut, (c)
8081—	.03	Needle Bar Screw Nut Washer
8082—	.22	Needle Bar Bent Thread Pin, (w)
8083—	.05	Needle Bar Spline
8084—	.24	Needle Bar Bushing, (Special)
6153—	.15	Needle Wrench
8085—	.30	Shaft Bushing, (Special)
8086—		Shaft, 12 stitch,
8087—	2.00	Shaft, 7 stitch, (H)
8088—		Shaft, 5 stitch
8089—		Shaft, 3 stitch
8090—	.45	Shaft Eccentric, 7 Stitch
8091—	.45	Shaft Eccentric, 5 Stitch
8092—	.45	Shaft Eccentric, 3 Stitch
6120—	.06	Shaft Eccentric Screw, same as Hook Screw
8093—	1.00	Shaft Eccentric Plug, 12 Stitch
8094—	1.00	Shaft Eccentric Plug, 7 Stitch
8095—	.39	Shaft Shield, (J)
8096—	.06	Shaft Shield Screw
8097—	.25	Speed Wheel and Screws
8098—	.10	Spool Stand Thread Pin, (t)
8099—	.04	Spool Stand Velvet Washer
8100—	.10	Spool Pin, (s)
8101—	2.50	Tension, Complete
8102—	.75	Tension Stud, (Y)
8103—	.02	Tension Washer, Cloth
	.60	Tension Washer, Glass, (Z) Same as 8063.
8105—	.10	Tension Washer, Iron
8106—	.03	Tension Spring
8107—	.05	Tension Spring Cap
6220—	.20	Thumb Screw, (K), 1 $\frac{5}{16}$ " to 6"
8108—	.05	Thumb Screw Washer, (g)
8109—	.34	Thumb Screw Bushing
8110—	2.67	Wheel, (G)
6230—	.05	Wheel Screw



CAUTION ABOUT NEEDLES



Buy Needles of us direct or at our Branch Offices, and you will be sure to get only "Genuine." You are almost certain to get worthless imitations (called Willcox & Gibbs needles) from Sewing Machine agents and dealers, and from fancy goods stores. Needles not bearing both stamps **W. & G.** and [Pat. Mar. 19, 1861] as shown above are spurious.

The perfect, or even satisfactory working of our machine, depends upon using **Genuine** Needles.

Needles offered at less than our prices are **not genuine**, are liable to injure the machine, and cause great dissatisfaction and annoyance in use.

HOME OFFICE

WILLCOX & GIBBS SEWING MACHINE CO.

658 Broadway, New York City, N. Y.